



<b>sabena</b> <sup>®</sup> <b>B707</b>	Module: LWR FUS / EMPENA	A/C Reg :	Check :	 <b>21E0000506</b>
	Oper. : RT-MP LC			
	Type : * ZONAL INSP*	Issuer : A43710	Cert.St.: 24828	<b>Page 1 of 2</b>
Spec. : MECHANIC	Release Date: 11.10.2001			

AD 91-07-07 rev 6943                      CENTER SECT FRONT SPAR UP LUG INSP

		MAINT	RII/INSP
Execution / Start Date:			
End Date:			

<b>sabena</b> B707	Module: LWR FUS / EMPENA	A/C Reg :	Check :	 21E0000506 Page 2 of 2
	Oper. : RT-MP LC	Issuer : A43710	Cert.St.: 24828	
	Type : * ZONAL INSP*	Release Date: 11.10.2001		
	Spec. : MECHANIC			

AD 91-07-07 rev 6943      CENTER SECT FRONT SPAR UP LUG INSP

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		E3 E4 S	MEC	AD 91-07-07 rev 6943 AD 92-04-04 rev 8170 MMS-328 533540 03000 rev 15/05/01 SB 55-2959 rev . SB 55-3067 rev . SB 55A3482 rev 1.		
Check: C						
Zones:						
Access: 1185 L						

**CONDITION:** Panels in bulkhead fwd of front spar —>OPEN.

**CENTER SECTION FRONT SPAR UPPER LUGS INSPECTION.**

-Per SB A3482 rev 1 fig 2

1. Close visual inspection of the lugs for cracks with special attention to the fwd inb and aft outb areas of the lugs (fig 2).
2. If no cracks are found: Ultrasonic inspection (Doc. D6-48023 P4, Subj 55-10-07, Fig 1&2).
3. Apply BMS 3-23.




FIGURE 2. CENTER SECTION LUG INSPECTION