



sabena [®] B707	Module: MLG WW + DOORS	A/C Reg :	Check :	 11E0000504
	Oper. : RT-MP LC			
	Type : * ZONAL INSP*	Issuer : A59513	Cert.St.: 50516	Page 1 of 2
Spec. : MECH. INSP	Release Date: 03.05.2011			

RH MAIN WW HYD COMPO INSP

Execution / Start Date:	
End Date:	

MAINT	RII/INSP

sabena B707	Module: MLG WW + DOORS	A/C Reg :	Check :	 11E0000504 Page 2 of 2
	Oper. : RT-MP LC			
	Type : * ZONAL INSP*	Issuer : A59513	Cert.St.: 50516	
	Spec. : MECH. INSP	Release Date: 03.05.2011		

RH MAIN WW HYD COMPO INSP

					MAINT	RII/INSP	
Nr.	Hardtime	Task	Spec.	Related Documents			
1.		BT1	INS	CHP 29-10-07 rev 6 CPM D6-82560 rev .. MMS-328 290008 00102 rev 15/06/09 MPD 04-29-10 rev .			
Check: C1							
Zones: 136							
Access:							
NRC YES <input type="radio"/> NO <input type="radio"/>		IF YES, NUMBER(S):					

RH MAIN WHEEL WELL, HYDRAULIC SYSTEM COMPONENTS INSPECTION.

Close visual inspection of hydraulic system components including plumbing, clamps and brackets for white corrosion products on aluminium or black pits on corrosion resistant steel. When clamps are removed, inspect the tubing visually for signs of deterioration of the polyurethane coating. A loose nylon clamp may be indication that coating has worn and needs replacement.