



<b>sabena</b> <sup>®</sup> <b>B707</b>	Module: MLG WW + DOORS	A/C Reg :	Check :	 <b>11F2000512</b>
	Oper. : RT-MP LC			
	Type : MEC-INSP	Issuer : A45831	Cert.St.: 24828	
Spec. : MECHANIC	Release Date: 02.10.2001		<b>Page 1 of 2</b>	

AD 63-11-01 rev 568                      LH MLG TRUCK BEAM INSP

		MAINT	RII/INSP
Execution / Start Date:			
End Date:			

AD 63-11-01 rev 568                      LH MLG TRUCK BEAM INSP

<b>sabena</b> <b>B707</b>	Module: MLG WW + DOORS	A/C Reg :	Check :	 <b>11F2000512</b> <b>Page 2 of 2</b>
	Oper. : RT-MP LC	Issuer : A45831	Cert.St.: 24828	
	Type : MEC-INSP	Release Date: 02.10.2001		
Spec. : MECHANIC				

AD 63-11-01 rev 568      LH MLG TRUCK BEAM INSP

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		E3	MEC	AD 63-11-01 rev 568 MMS-328 321005 00101 rev 15/05/01 SB 32-142 rev .		
Check: C						
Zones: 135						
Access:						

**LH MLG TRUCK BEAM AND TRUCK BEAM PROTECTION SHIELD INSPECTION.**

1. Clean all visible parts on MLG truck beam:
2. Close visual inspection of truck beam using mirror as necessary and a strong light to detect any evidence of jack marks, scratches gouges, corrosion or impact dents. Remove any straps around the beam which show evidence of damage.

Particular attention shall be given to:

- The lower section of the beam for evidence of jack marks caused by jack slippage or improperly placed jack.
- The FWD area of the beam where contact is possible with the torsion link pivot pin retaining bolt.
- To the AFT area of the beam where contact is possible with the shock strut inner cylinder upon snubber failure.

