



<b>sabena</b> <sup>®</sup> <b>B707</b>	Module: LWR FUS / EMPENA	A/C Reg :	Check :	 <b>21F1000508</b>
	Oper. : RT-MP LC			
	Type : REI-INSP	Issuer : A43710	Cert.St.: 24828	<b>Page 1 of 2</b>
Spec. : ELECTRICIAN	Release Date: 11.10.2001			

**FWD LOW CARGO DOOR WARN SW INSP**

Execution / Start Date:	
End Date:	

MAINT	RII/INSP


<b>sabena</b> <b>B707</b>	Module: LWR FUS / EMPENA	A/C Reg :	Check :	 <b>21F1000508</b> <b>Page 2 of 2</b>
	Oper. : RT-MP LC			
	Type : REI-INSP	Issuer : A43710	Cert.St.: 24828	
	Spec. : ELECTRICIAN	Release Date: 11.10.2001		

**FWD LOW CARGO DOOR WARN SW INSP**


					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		E3 I1 W1	REI	MMS-328 527010 03020 rev 15/05/01		
Check: C						
Zones: 144						
Access:						

**FWD LOWER CARGO DOOR WARNING SWITCH INSTALLATION INSPECTION.**

1. Remove cover above door warning switch.
2. Detailed visual inspection for condition obvious defects and security of installation of the microswitches, pins, plungers, brackets, clamp and associated wiring of the FWD lower cargo door.
3. Reinstall cover above switch.



**FWD CARGO COMPARTMENT  
INTERIOR ACCESS DOOR SWITCH**



**TYPICAL ENTRY, GALLEY  
AND CARGO DOOR SWITCH**