



<b>sabena</b> <sup>®</sup> <b>B707</b>	Module: LWR FUS / EMPENA	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : STRUCT-INSP	Issuer : A59513	Cert.St.: 46928	21F3000505
Spec. : MECH. INSP	Release Date: 22.11.2005		Page 1 of 4	

AD 85-12-01 rev . FWD LWR CARGO DOOR CUTOUT INSP

		MAINT	RII/INSP
Execution / Start Date:			
End Date:			

AD 85-12-01 rev . FWD LWR CARGO DOOR CUTOUT INSP


<b>sabena</b> B707	Module: LWR FUS / EMPENA	A/C Reg :	Check :	 21F3000505 Page 2 of 4
	Oper. : RT-MP LC			
	Type : STRUCT-INSP	Issuer : A59513	Cert.St.: 46928	
	Spec. : MECH. INSP	Release Date: 22.11.2005		

AD 85-12-01 rev . FWD LWR CARGO DOOR CUTOUT INSP

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.	21786 CYC	E3	INS	AD 85-12-01 R1 rev 5439 MMS-328 530180 02010 rev 15.07.05 SSID 53-A45-08/A rev .		
Check: C1						
Zones: 113						
Access:						
NRC YES <input type="radio"/> NO <input type="radio"/>		IF YES, NUMBER(S):				


**FUSELAGE FWD LOWER CARGO COMPARTMENT DOOR CUTOUT INSPECTION.**

Inspect close visual, external for cracks in fuselage framing, skin, sill, door stop support fittings and doubler around door cutout. Pay particular attention to the cutouts exposed edge and doubler attach fastener areas surrounding the cutout on the FWD LOWER CARGO DOOR CUTOUT.



FUSELAGE LOWER CARGO COMPARTMENT CUTOUT INSPECTION.

AD 85-12-01 rev . FWD LWR CARGO DOOR CUTOUT INSP


<b>sabena</b> B707	Module: LWR FUS / EMPENA	A/C Reg :	Check :	 21F3000505 Page 3 of 4
	Oper. : RT-MP LC			
	Type : STRUCT-INSP	Issuer : A59513	Cert.St.: 46928	
	Spec. : MECH. INSP	Release Date: 22.11.2005		

AD 85-12-01 rev . FWD LWR CARGO DOOR CUTOUT INSP

					MAINT	RII/INSP	
Nr.	Hardtime	Task	Spec.	Related Documents			
2.	21884 CYC	E3	INS	AD 85-12-01 R1 rev 5439 MMS-328 530180 02010 rev 15.07.05 SSID 53-A45-08/A rev .			
Check: C1							
Zones: 113							
Access:							
NRC YES <input type="radio"/> NO <input type="radio"/>		IF YES, NUMBER(S):					


**FUSELAGE FWD LOWER CARGO COMPARTMENT DOOR CUTOUT INSPECTION.**

Inspect close visual, external for cracks in fuselage framing, skin, sill, door stop support fittings and doubler around door cutout. Pay particular attention to the cutouts exposed edge and doubler attach fastener areas surrounding the cutout on the FWD LOWER CARGO DOOR CUTOUT.



FUSELAGE LOWER CARGO COMPARTMENT CUTOUT INSPECTION.

AD 85-12-01 rev . FWD LWR CARGO DOOR CUTOUT INSP


<b>sabena</b> B707	Module: LWR FUS / EMPENA	A/C Reg :	Check :	 21F3000505 Page 4 of 4
	Oper. : RT-MP LC	Issuer : A59513	Cert.St.: 46928	
	Type : STRUCT-INSP	Release Date: 22.11.2005		
Spec. : MECH. INSP				

AD 85-12-01 rev . FWD LWR CARGO DOOR CUTOUT INSP

					MAINT	RII/INSP	
Nr.	Hardtime	Task	Spec.	Related Documents			
3.		E3	INS	AD 85-12-01 R1 rev 5439 MMS-328 530180 02010 rev 15.07.05 SSID 53-A45-08/A rev .			
Check: C1							
Zones: 113							
Access:							
NRC YES <input type="radio"/> NO <input type="radio"/>		IF YES, NUMBER(S):					

**FUSELAGE FWD LOWER CARGO COMPARTMENT DOOR CUTOUT INSPECTION.**

Inspect close visual, external for cracks in fuselage framing, skin, sill, door stop support fittings and doubler around door cutout. Pay particular attention to the cutouts exposed edge and doubler attach fastener areas surrounding the cutout on the FWD LOWER CARGO DOOR CUTOUT.



FUSELAGE LOWER CARGO COMPARTMENT CUTOUT INSPECTION.