



sabena [®] B707	Module: LH WING + FL CTR	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : MEC-INSP	Issuer : A59513	Cert.St.: 50516	31F2000525
Spec. : MECH. INSP	Release Date: 05.05.2011		Page 1 of 2	

LH WING FS UPPER/LOWER CHORD INSPECTION

Execution / Start Date:	
End Date:	

MAINT	RII/INSP

sabena B707	Module: LH WING + FL CTR	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : MEC-INSP	Issuer : A59513	Cert.St.: 50516	31F2000525
Spec. : MECH. INSP	Release Date: 05.05.2011		Page 2 of 2	

LH WING FS UPPER/LOWER CHORD INSPECTION

					MAINT	RII/INSP	
Nr.	Hardtime	Task	Spec.	Related Documents			
1.		E3	INS	MMS-328 574040 01003 rev 16/10/2009			
Check: B							
Zones: 562, 563, 564							
Access:							
NRC YES <input type="radio"/> NO <input type="radio"/>		IF YES, NUMBER(S):					

Perform a close visual inspection of LH wing front spar upper/lower chord for corrosion, cracks, blistering, raised or rough spots in the paint finish in the following areas:

- Chords at inboard & outboard nacelle attachment points
- Chord vertical flange around the edges of all slat actuator support fittings.
- Visually inspect entire front spar for deterioration of CIC. Restore as required.