



<b>sabena</b> <sup>®</sup> <b>B707</b>	Module: MLG WW + DOORS	A/C Reg :	Check :	 <b>11F4000500</b>
	Oper. : RT-MP LC			
	Type : NDT INSP	Issuer : A45831	Cert.St.: 24828	<b>Page 1 of 2</b>
Spec. : MECHANIC	Release Date: 02.10.2001			

**MLG & DOOR INSP**

Execution / Start Date:	
End Date:	

MAINT	RII/INSP

<b>sabena</b> <b>B707</b>	Module: MLG WW + DOORS	A/C Reg :	Check :	 <b>11F4000500</b> <b>Page 2 of 2</b>
	Oper. : RT-MP LC	Issuer : A45831	Cert.St.: 24828	
	Type : NDT INSP	Release Date: 02.10.2001		
	Spec. : MECHANIC			

**MLG & DOOR INSP**

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		E4	MEC	MMS-328 321002 00101 rev 15/05/01 MMS-328 321002 00102 rev 15/05/01 SAB 707-762 rev .		
<b>Check: C</b>						
<b>Zones: 135, 136</b>						
<b>Access:</b>						

**MAIN LANDING GEARS AND DOORS INSPECTION.**

1. Clean and degrease MLG side strut lower segment lower lug.
  - LH MLG.
  - RH MLG.
2. Eddy Current inspection of MLG side strut lower segment lower lug.
  - Inspect for cracks as indicted arround bolt head, nut and radius which joint flat portion to lateral faces on left and right main landing gear.
  - LH MLG.
  - RH MLG.

