



sabena B707	Module: MLG WW + DOORS	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : SERVICING	Issuer : A43710	Cert.St.: 24828	11H1000504
Spec. : MECHANIC	Release Date: 16.10.2001		Page 1 of 2	

MAIN CARGO DOOR HYD PUMP FILTER REPL

Execution / Start Date:	
End Date:	

MAINT **RII/INSP**

Pos	Mat. Type	P/N	IDN	Description	Qty	Unit
1	CONSUM	10-60592-3	123980	FILTER	1.00	EA
1	CONSUM	BACP11G1	882331	PACKING	1.00	EA

sabena B707	Module: MLG WW + DOORS	A/C Reg :	Check :	 11H1000504
	Oper. : RT-MP LC	Issuer : A43710	Cert.St.: 24828	
	Type : SERVICING	Release Date: 16.10.2001	Page 2 of 2	
Spec. : MECHANIC				

MAIN CARGO DOOR HYD PUMP FILTER REPL

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		S	MEC	MMS-328 291007 00100 rev 15/05/01		
Check: C						
Zones: 135						
Access:						

MAIN CARGO DOOR HYDRAULIC PUMP FILTER ELEMENT REPLACEMENT.

Replace filter element of the MAIN CARGO DOOR HYDRAULIC PUMP.

1. Depressurize main cargo door hydraulic system: Move manual lever on main cargo door control valve to opposite position.
2. Remove filter case and remove element from case.
3. clean case.
4. position and install new filter element in case.
5. install new packing and install case.

