



sabena B707	Module: ENGINE 1	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : SERVICING	Issuer : A59513	Cert.St.: 50516	N1H1000507
Spec. : MECHANIC	Release Date: 19.05.2010		Page 1 of 2	

ENG #1 FUEL FILT DIFF PRESS SW REPL

Execution / Start Date:	
End Date:	

MAINT **RII/INSP**

Pos	Mat. Type	P/N	IDN	Description	Qty	Unit
1	CONSUM	MS 9967-007	424687	PACKING	1.00	EA
1	CONSUM	MS 9967-008	549520	PACKING	1.00	EA
1	CONSUM	MS 9021-005	865753	SEAL	2.00	EA
1	CONSUM	377102	120281	SWITCH ASSY	1.00	EA

sabena B707	Module: ENGINE 1	A/C Reg :	Check :	 N1H1000507 Page 2 of 2
	Oper. : RT-MP LC			
	Type : SERVICING	Issuer : A59513	Cert.St.: 50516	
	Spec. : MECHANIC	Release Date: 19.05.2010		

ENG #1 FUEL FILT DIFF PRESS SW REPL

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		S	MEC	MMS-328 731002 A0201 rev 06.06.02		
Check: C						
Zones: 451						
Access:						
NRC YES <input type="radio"/> NO <input type="radio"/>		IF YES, NUMBER(S):				
NRC YES <input type="radio"/> NO <input type="radio"/>		IF YES, NUMBER(S):				

ENGINE #1 FUEL FILTER DIFFERENTIAL PRESSURE SWITCH REPLACEMENT.

1. REMOVAL:

- Disconnect electrical leads.
- Remove 4 bolts & washers securing differential fluid pressure switch to fuel de-icing filter cover & remove switch.

2. INSTALLATION:

- Install (replaced) differential fluid pressure switch & secure with 4 bolts & washers.
- Torque & lockwire bolts.
- Connect electrical leads.

3. CHECK FOR LEAKS.

