



<b>sabena</b> <b>B707</b>	Module: ENGINE 2	A/C Reg :	Check :	
	Oper. : RT-MP LC	Issuer : A59513	Cert.St.: 50516	
	Type : MEC-INSP	Release Date: 30.03.2010	<b>Page 1 of 2</b>	
Spec. : MECH. INSP				

**ENG 2 CSD MAGN PLUG INSP**

Execution / Start Date:	
End Date:	

**MAINT**      **RII/INSP**

Pos	Mat. Type	P/N	IDN	Description	Qty	Unit
1	CONSUM	M83248-1-902	340987	PACKING	1.00	

<b>sabena</b> <b>B707</b>	Module: ENGINE 2	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : MEC-INSP	Issuer : A59513	Cert.St.: 50516	<b>O1F2000501</b>
	Spec. : MECH. INSP	Release Date: 30.03.2010		<b>Page 2 of 2</b>

**ENG 2 CSD MAGN PLUG INSP**

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		E3	INS	MMS-328 241004 00102 rev 15/05/01		
Check: B						
Zones: 452						
Access:						
<b>ENGINE 2 CSD:</b>						
1. <u>GENERATOR DRIVE</u> : CHECK CSD MAGNETIC PLUG FOR METAL PARTICLES.						
A. Remove CSD MAGNETIC PLUG.						
B. Perform inspection on MAGNETIC PLUG FOR METAL PARTICLES.						
C. Reinstall plug with NEW "O"-RING & install lockwire.						