



<b>sabena</b> <sup>®</sup> <b>B707</b>	Module: UPPR FUS /RADOME	A/C Reg :	Check :	 <b>11F2000502</b>
	Oper. : RT-MP LC			
	Type : MEC-INSP	Issuer : A43710	Cert.St.: 24828	<b>Page 1 of 2</b>
Spec. : MECHANIC	Release Date: 16.10.2001			

**MAIN CARGO DOOR MAN SAFETY VLV LEAK CHECK**

Execution / Start Date:	
End Date:	

MAINT	RII/INSP

<b>sabena</b> <b>B707</b>	Module: UPPR FUS /RADOME	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : MEC-INSP	Issuer : A43710	Cert.St.: 24828	11F2000502
Spec. : MECHANIC	Release Date: 16.10.2001		Page 2 of 2	

**MAIN CARGO DOOR MAN SAFETY VLV LEAK CHECK**

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		F2	MEC	MMS-328 523210 05002 rev 15/05/01		
Check: C1						
Zones: 249						
Access:						
<p><b><u>MAIN CARGO DOOR, MANUALLY SAFETY VALVE LEAK CHECK.</u></b></p> <p>1. Pressurise cargo door system by AUXILIARY 1 pump.</p> <p>2. Put manual safety valve in CLOSED position.</p> <p>3. Put control sw. in OPEN position. Cargo door should not move or open.</p>						

**MAIN CARGO DOOR MAN SAFETY VLV LEAK CHECK**