



sabena [®] B707	Module: UPPR FUS /RADOME	A/C Reg :	Check :	 11K0000501
	Oper. : RT-MP LC			
	Type : *OPER./FUNC. CHE	Issuer : A43710	Cert.St.: 24828	Page 1 of 2
Spec. : MECHANIC	Release Date: 16.10.2001			

MAIN CARGO DOOR HYD SOV F/C

Execution / Start Date:	
End Date:	

MAINT	RII/INSP

sabena B707	Module: UPPR FUS /RADOME	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : *OPER./FUNC. CHE	Issuer : A43710	Cert.St.: 24828	11K0000501
Spec. : MECHANIC	Release Date: 16.10.2001		Page 2 of 2	

MAIN CARGO DOOR HYD SOV F/C

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		F1	MEC	MMS-328 523210 05003 rev 15/05/01		
Check: C1						
Zones: 249						
Access:						
<u>MAIN CARGO DOOR, HYDRAULIC SHUT OFF VALVE FUNCTIONAL CHECK.</u>						
Perform hydraulic shutoff valve functional check:						
1. Pressurise cargo door system by AXILIARY1 pump.						
2. Put isolation switch door in ON position.						
3. Put manual safety valve in OPEN position.						
4. Pull breaker on P5 safety relay.						
5. Put control switch in OPEN position. Cargo door should not move or open.						
6. After check, restaure airplane in normal configuration.						