



sabena [®] B707	Module: LWR FUS / EMPENA	A/C Reg :	Check :	 21F1000506
	Oper. : RT-MP LC			
	Type : REI-INSP	Issuer : A43710	Cert.St.: 24828	Page 1 of 2
Spec. : ELECTRICIAN	Release Date: 11.10.2001			

AFT LOW FWD CARGO DOOR WARN SW INSP

		MAINT	RII/INSP
Execution / Start Date:			
End Date:			


sabena B707	Module: LWR FUS / EMPENA	A/C Reg :	Check :	 21F1000506
	Oper. : RT-MP LC			
	Type : REI-INSP	Issuer : A43710	Cert.St.: 24828	Page 2 of 2
Spec. : ELECTRICIAN	Release Date: 11.10.2001			

AFT LOW FWD CARGO DOOR WARN SW INSP

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		E3 I1 W1	REI	MMS-328 527010 03030 rev 15/05/01		
Check: C						
Zones: 145						
Access:						

AFT LOWER CAGO FWD DOOR WARNING SWITCH INSTALLATION INSPECTION.

1. Remove cover above door warning switch.
2. Detailed visual inspection for condition obvious defects and security of installation of the microswitches, pins, plungers, brackets, clamp and associated wiring of the AFT aft lower cargo fwd door.
3. Reinstall cover above switch.



TYPICAL ENTRY, GALLEY AND CARGO DOOR SWITCH