



sabena [®] B707	Module: LH WING + FL CTR	A/C Reg :	Check :	 31F3000513
	Oper. : RT-MP LC	Issuer : A43710	Cert.St.: 24828	
	Type : STRUCT-INSP	Release Date: 05.10.2001		Page 1 of 2
Spec. : MECH. INSP				

LH WING OUTB DRY BAY LWR SKIN INSP

Execution / Start Date:	
End Date:	

MAINT	RII/INSP

sabena B707	Module: LH WING + FL CTR	A/C Reg :	Check :	 31F3000513
	Oper. : RT-MP LC	Issuer : A43710	Cert.St.: 24828	
	Type : STRUCT-INSP	Release Date: 05.10.2001	Page 2 of 2	
Spec. : MECH. INSP				

LH WING OUTB DRY BAY LWR SKIN INSP

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		E3	INS	MMS-328 570150 01000 rev 15/05/01 SB 707-57-3429 rev 1		
Check: C						
Zones:						
Access:						

WING OUTB DRY BAY LOWER SKIN INSPECTION.

Lower wing skin at OUTB dry bay cutout at WS 672, visually inspect for cracks originating in the nutplate holes. (See Fig. 1).

