



<b>sabena</b> <b>B707</b>	Module: RH WING + FL CTR	A/C Reg :	Check :	 <b>41F4000514</b>
	Oper. : RT-MP LC			
	Type : NDT INSP	Issuer : A59513	Cert.St.: 46928	
Spec. : NDT INSP	Release Date: 22.11.2006		Page 1 of 7	

**RH WING LWR PANEL SPANWISE SPLICE NDT INSPECTION**

Execution / Start Date:	
End Date:	

MAINT	RII/INSP

<b>sabena</b> <b>B707</b>	Module: RH WING + FL CTR	A/C Reg :	Check :	 <b>41F4000514</b>
	Oper. : RT-MP LC	Issuer : A59513	Cert.St.: 46928	
	Type : NDT INSP	Release Date: 22.11.2006	Page 2 of 7	

**RH WING LWR PANEL SPANWISE SPLICE NDT INSPECTION**


					<b>MAINT</b>	<b>RII/INSP</b>
Nr.	Hardtime	Task	Spec.	Related Documents		
1.	19305 CYC	E4	NDT	AD 85-12-01 R1 rev 5439 MMS-328 572080 01001 rev 15.07.05 SSID 57-A40-05/B1 rev P		
<b>Check:</b> C1						
<b>Zones:</b> 673, 674						
<b>Access:</b> 1326R, 1327R, 1328R, 1329R, 1330R, 1331R, 1332R, 1333R						
NRC YES <input type="radio"/> NO <input type="radio"/>		IF YES, NUMBER(S): .....				

**RH WING LWR PANEL SPANWISE SPLICE BBL 70.50 TO OUTBOARD NACELLE.**

**RH WING LWR PANEL SPANWISE SPLICE BBL 70.50 TO OUTBOARD NACELLE, S-4 S-8, S-14, S-18 & SPECIFIED TYPICAL STRINGERS.**


H.F.E.C. Internal inspection inner horizontal flange of splice stringers for cracks at rib to stringer attachments.

Refer. DOC D6-48023 Part 6,57-10-07 Fig 10




**RH WING LWR PANEL SPANWISE SPLICE NDT INSPECTION**



<b>sabena</b> <b>B707</b>	Module: RH WING + FL CTR	A/C Reg :	Check :	 <b>41F4000514</b> <b>Page 4 of 7</b>
	Oper. : RT-MP LC	Issuer : A59513	Cert.St.: 46928	
	Type : NDT INSP	Release Date: 22.11.2006		
Spec. : NDT INSP				


**RH WING LWR PANEL SPANWISE SPLICE NDT INSPECTION**




MAINT	RII/INSP

**RH WING LWR PANEL SPANWISE SPLICE NDT INSPECTION**




<b>sabena</b> <b>B707</b>	Module: RH WING + FL CTR	A/C Reg :	Check :	 <b>41F4000514</b> <b>Page 6 of 7</b>
	Oper. : RT-MP LC	Issuer : A59513	Cert.St.: 46928	
	Type : NDT INSP	Release Date: 22.11.2006		

**RH WING LWR PANEL SPANWISE SPLICE NDT INSPECTION**




**MAINT**      **RII/INSP**

**RH WING LWR PANEL SPANWISE SPLICE NDT INSPECTION**

<b>sabena</b> B707	Module: RH WING + FL CTR	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : NDT INSP	Issuer : A59513	Cert.St.: 46928	41F4000514
	Spec. : NDT INSP	Release Date: 22.11.2006		Page 7 of 7

**RH WING LWR PANEL SPANWISE SPLICE NDT INSPECTION**

	MAINT	RII/INSP
 <p style="text-align: center;">WING LOWER PANEL SPANWISE SPLICE INSPECTION</p>		

**RH WING LWR PANEL SPANWISE SPLICE NDT INSPECTION**