



<b>sabena</b> <b>B707</b>	Module: CABIN + WINDOWS	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : *DETAIL CLEAN*	Issuer : A43710	Cert.St.: 24828	91D0000501
Spec. : CABIN	Release Date: 11.10.2001		Page 1 of 2	

**AFT RH TOILET CLEAN & DISINFECT**

Execution / Start Date:	
End Date:	

**MAINT**      **RII/INSP**

Pos	Mat. Type	P/N	IDN	Description	Qty	Unit
1	FL & CH	Cee Bee ALKO		Cleaning Agent	0.00	
1	FL & CH	HAC		Disinfecting Agent	0.00	

<b>sabena</b> B707	Module: CABIN + WINDOWS	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : *DETAIL CLEAN*	Issuer : A43710	Cert.St.: 24828	91D0000501
Spec. : CABIN	Release Date: 11.10.2001		Page 2 of 2	

**AFT RH TOILET CLEAN & DISINFECT**

					<b>MAINT</b>	<b>RII/INSP</b>
<b>Nr.</b>	<b>Hardtime</b>	<b>Task</b>	<b>Spec.</b>	<b>Related Documents</b>		
1.		S	CAB	MMS-328 383003 00102 rev 15/05/01		
<b>Check: B</b>						
<b>Zones: 228</b>						
<b>Access:</b>						

**AFT TOILET RH:**

PERFORM CLEANING & DISINFECTION OF LAVATORIE FLUSH SYSTEM

PROCEDURE: (SN TECHN. STD MANUAL 4724)

**A. CLEANING:**

1. Drain waste tank.
2. Fill up the waste tank with the "Prime charge" amount of water.
3. Add Cee Bee ALKO at the rate of 1 liter ALKO to 2 liters of water via the toilet bowl.
4. Operate all flush switches at least 5 times to ensure contact of ALKO solution with all areas.
5. Repeat step 4 several times during the next 2 hours.
6. Drain the waste tank.
7. Rinse the toilet system by filling the waste tank up to 1/2 of its full capacity & operating all flush sw's at least 5 times.
8. Drain the waste tank.

**B. DISINFECTION:**

1. Fill up the waste tank with the "Prime charge" amount of water.
2. Add HAC at the rate of 10 ml HAC to 1 liter of water via the toilet bowl.
3. Operate all flush sw's at least 5 times to ensure contact of HAC with all areas.
4. Repeat step 3 after 1/2 hour.
5. After another 1/2 hour drain the waste tank