



sabena [®] B707	Module: MLG WW + DOORS	A/C Reg :	Check :	 11E0000503
	Oper. : RT-MP LC			
	Type : * ZONAL INSP*	Issuer : A43710	Cert.St.: 24828	Page 1 of 2
Spec. : MECHANIC	Release Date: 15.10.2001			

AD 94-10-06 rev 8913

RH MLG TRUNION SUP FIT INSP

		MAINT	RII/INSP
Execution / Start Date:			
End Date:			

sabena B707	Module: MLG WW + DOORS	A/C Reg :	Check :	 11E0000503 Page 2 of 2
	Oper. : RT-MP LC	Issuer : A43710	Cert.St.: 24828	
	Type : * ZONAL INSP*	Release Date: 15.10.2001		
Spec. : MECHANIC				

AD 94-10-06 rev 8913 RH MLG TRUNION SUP FIT INSP

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		E3 S	MEC	AD 94-10-06 rev 8913 MMS-328 575020 01000 rev 15/05/01 SB 57-28-37 FIG 1 rev 5		
Check: C						
Zones:						
Access:						

RH MLG TRUNION SUPPORT FITTINGS INSPECTION.

1. Clean RH MLG trunion FWD & AFT support fittings.
2. Close visual inspection of RH MLG trunion FWD & AFT support fittings.
3. Apply BMS 3-23 per CPM 57-40-07 on RH MLG trunion FWD & AFT support fittings.

