


sabena B707	Module: TAIL CMPT	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : SERVICING	Issuer : A59513	Cert.St.: 50516	M1H1000500
Spec. : MECHANIC	Release Date: 19.05.2010		Page 1 of 2	


FLIGHT CONT CABLES TAIL COMP CLEAN INSP LUB

Execution / Start Date:	
End Date:	

MAINT **RII/INSP**

Pos	Mat. Type	P/N	IDN	Description	Qty	Unit
1	FL & CH	BMS 3-33		GREASE	0.00	

FLIGHT CONT CABLES TAIL COMP CLEAN INSP LUB

sabena B707	Module: TAIL CMPT	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : SERVICING	Issuer : A59513	Cert.St.: 50516	M1H1000500
	Spec. : MECHANIC	Release Date: 19.05.2010		Page 2 of 2

FLIGHT CONT CABLES TAIL COMP CLEAN INSP LUB

					MAINT	RII/INSP	
Nr.	Hardtime	Task	Spec.	Related Documents			
1.		E2 S	MEC	MMS-328 270012 01000 rev 15/05/01			
Check: C							
Zones: 138							
Access:							
NRC YES <input type="radio"/> NO <input type="radio"/>		IF YES, NUMBER(S):					

FLIGHT CONTROL CABLES IN TAIL COMPARTMENT : CLEAN, INSPECT & LUBRICATION.

- With dry cloth clean & inspect control cables in TAIL COMPARTMENT:
 - The flight control cables for broken wires.
 - Associated pulleys, brackets & mechanisms for condition & security of installation.
- Lubricate flight control cables with GREASE AEROSHELL 16 in the TAIL COMPARTMENT.

NOTE: NOT APPLICABLE TO NYLON COATED & STAINLESS STEEL CONTROL CABLES