


sabena B707	Module: TAIL CMPT	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : SERVICING	Issuer : A59513	Cert.St.: 46928	M1H1000501
Spec. : MECH. INSP	Release Date: 13.04.2005		Page 1 of 2	


FLIGHT CONT CABLES TAIL COMP CLEAN INSP LUB

Execution / Start Date:	
End Date:	

MAINT RII/INSP

Pos	Mat. Type	P/N	IDN	Description	Qty	Unit
1	FL & CH	AEROSHELL 16		GREASE	0.00	

FLIGHT CONT CABLES TAIL COMP CLEAN INSP LUB

sabena B707	Module: TAIL CMPT	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : SERVICING	Issuer : A59513	Cert.St.: 46928	M1H1000501
	Spec. : MECH. INSP	Release Date: 13.04.2005		Page 2 of 2

FLIGHT CONT CABLES TAIL COMP CLEAN INSP LUB

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		E3 S	INS	MMS-328 270013 01000 rev 15/05/01		
Check: S						
Zones:						
Access:						
<p><u>FLIGHT CONTROL CABLES IN TAIL COMP AREA: CLEAN, INSPECT FOR WEAR, BROKEN WIRES & CORROSION & & LUBRICATION.</u></p> <p>1. With dry cloth clean & inspect control cables in TAIL COMP AREA:</p> <ul style="list-style-type: none"> - The flight control cables for wear, broken wires & corrosion. - Associated pulleys, brackets & mechanisms for condition & security of installation. <p>2. Lubricate flight control cables with GREASE AEROSHELL 16 in TAIL COMP AREA.</p> <p><u>NOTE: NOT APPLICABLE TO NYLON COATED & STAINLESS STEEL CONTROL CABLES</u></p>						