



<b>sabena</b> <b>B707</b>	Module: ENGINE 1	A/C Reg :	Check :	 <b>N1A0000500</b>
	Oper. : RT-MP LC			
	Type : *INCOMING*	Issuer : A43710	Cert.St.: 24828	<b>Page 1 of 2</b>
Spec. : MECHANIC	Release Date: 15.10.2001			

REF H 40 REQ rev 0      **ENG 1 T/R CHECK FOR LEAKS AT A/C ENTRY**

		MAINT	RII/INSP
Execution / Start Date:			
End Date:			

REF H 40 REQ rev 0      **ENG 1 T/R CHECK FOR LEAKS AT A/C ENTRY**

<b>sabena</b> <b>B707</b>	Module: ENGINE 1	A/C Reg :	Check :	
	Oper. : RT-MP LC	Issuer : A43710	Cert.St.: 24828	
	Type : *INCOMING*	Release Date: 15.10.2001		
Spec. : MECHANIC				

**REF H 40 REQ rev 0                      ENG 1 T/R CHECK FOR LEAKS AT A/C ENTRY**

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		E3	MEC	REF H 40 REQ rev 0		
<b>Check:            C</b> <b>Zones:</b> <b>Access:</b>						
<b><u>AT A/C ENTRY.</u></b>  DO A OPERATIONAL TEST OF THRUST REVERSER & CHECK FOR LEAKS AT ALL ACTUATORS OF FWD & AFT THRUST REVERSER SYSTEM.  CHECK FOR CORRECT FUNCTIONAL OF LIGHTS IN COCKPIT						