




<b>sabena</b> <sup>®</sup> <b>B707</b>	Module: ENGINE 2	A/C Reg :	Check :	
	Oper. : RT-MP LC	Issuer : A43710	Cert.St.: 24828	
	Type : *INCOMING*	Release Date: 15.10.2001	<b>Page 2 of 2</b>	
Spec. : MECHANIC				

REF H 40 REQ rev 0      **ENG 2 T/R CHECK FOR LEAKS AT A/C ENTRY**

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		E3	MEC	REF H 40 REQ rev 0		
Check:      C						
Zones:						
Access:						
<b><u>AT A/C ENTRY.</u></b>						
DO A OPERATIONAL TEST OF THRUST REVERSER & CHECK FOR LEAKS AT ALL ACTUATORS OF FWD & AFT THRUST REVERSER SYSTEM.						
CHECK FOR CORRECT FUNCTIONAL OF LIGHTS IN COCKPIT						

REF H 40 REQ rev 0      **ENG 2 T/R CHECK FOR LEAKS AT A/C ENTRY**