



sabena [®] B707	Module: PYLON 2	A/C Reg :	Check :	 T1F2000502
	Oper. : RT-MP LC	Issuer : A43710	Cert.St.: 24828	
	Type : MEC-INSP	Release Date: 16.10.2001		Page 1 of 2
Spec. : MECH. INSP				

ENG #2 ENG MOUNT INSP

Execution / Start Date:	
End Date:	

MAINT	RII/INSP

ENG #2 ENG MOUNT INSP

sabena B707	Module: PYLON 2	A/C Reg :	Check :	 T1F2000502
	Oper. : RT-MP LC	Issuer : A43710	Cert.St.: 24828	
	Type : MEC-INSP	Release Date: 16.10.2001	Page 2 of 2	

ENG #2 ENG MOUNT INSP

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		E3	INS	MMS-328 544210 09001 rev 15/05/01		
Check: C						
Zones: 456						
Access:						

CONDITION: ENGINE COWLING REMOVED.

ENGINE #2 ATTACH FITTINGS INSPECTION.

Close visual inspection of the FWD engine mount thrust link connection fitting.
(strut lower spar at sta. 157).

