



| | | | | |
|---|--------------------------|-----------------|-----------------|--|
| sabena [®] B707 | Module: UPPR FUS /RADOME | A/C Reg : | Check : |  |
| | Oper. : RT-MP LC | | | |
| | Type : REI-INSP | Issuer : A43710 | Cert.St.: 24828 | 11F1000501 |
| Spec. : REI INSP | Release Date: 16.10.2001 | | Page 1 of 2 | |

UP & LOW ANTI COL LIGHTS INSP

| | |
|-------------------------|--|
| Execution / Start Date: | |
| End Date: | |

| MAINT | RII/INSP |
|-------|----------|
| | |

| | | | | |
|------------------------------|--------------------------|-----------------|-----------------|--|
| sabena B707 | Module: UPPR FUS /RADOME | A/C Reg : | Check : |  |
| | Oper. : RT-MP LC | | | |
| | Type : REI-INSP | Issuer : A43710 | Cert.St.: 24828 | 11F1000501 |
| Spec. : REI INSP | Release Date: 16.10.2001 | | Page 2 of 2 | |

UP & LOW ANTI COL LIGHTS INSP

| | | | | | MAINT | RII/INSP |
|---|----------|------|-------|-----------------------------------|-------|----------|
| Nr. | Hardtime | Task | Spec. | Related Documents | | |
| 1. | | E2 | INS | MMS-328 334002 00100 rev 15/05/01 | | |
| Check: C1 | | | | | | |
| Zones: 200 | | | | | | |
| Access: | | | | | | |
| <p><u>UPPER AND LOWER ANTI-COLLISION LIGHTS INSPECTION.</u></p> <p>Visual inspection of upper and lower anti-collision lights: Check for damage, cracked lenses, discoloration, cleanliness and general condition.</p> <p>- UPPER.</p> <p>- LOWER.</p> | | | | | | |