



sabena [®] B707	Module: UPPR FUS /RADOME	A/C Reg :	Check :	 11F4000500
	Oper. : RT-MP LC			
	Type : NDT INSP	Issuer : A43710	Cert.St.: 24828	Page 1 of 4
Spec. : NDT INSP	Release Date: 10.10.2001			

AFT ENTRY DOOR CUTOUT NDT INSP

Execution / Start Date:	
End Date:	

MAINT	RII/INSP


sabena B707	Module: UPPR FUS /RADOME	A/C Reg :	Check :	 11F4000500 Page 2 of 4
	Oper. : RT-MP LC	Issuer : A43710	Cert.St.: 24828	
	Type : NDT INSP	Release Date: 10.10.2001		
Spec. : NDT INSP				


AFT ENTRY DOOR CUTOUT NDT INSP

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.	29398 CYC	E3	NDT	AD 85-12-01 R1 rev 5439 MMS-328 530170 02002 rev 23/04/01 SSID 53-A40-06/IC rev N		
Check:						
Zones: 226						
Access: 1172 L						

AFT ENTRY DOOR CUTOUT NDT INSPECTION.

X-RAY external inspection of doubler sandwiched between fuselage skin and inner skin doubler. Skin lap areas. Frame, sill outer chord intersections. Fuselage skin beneath external steel stap. Skin and skin doubler around edge of door corners. Refer. DOC D6-48023 PART 2, 53-10-07 FIG 15.




sabena B707	Module: UPPR FUS /RADOME	A/C Reg :	Check :	 11F4000500 Page 3 of 4
	Oper. : RT-MP LC	Issuer : A43710	Cert.St.: 24828	
	Type : NDT INSP	Release Date: 10.10.2001		
Spec. : NDT INSP				


AFT ENTRY DOOR CUTOUT NDT INSP

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
2.	29487 CYC	E3	INS	AD 85-12-01 R1 rev 5439 MMS-328 530170 02002 rev 23/04/01 SSID 53-A40-06/IC rev N		
Check:						
Zones: 226						
Access: 1172 L						

AFT ENTRY DOOR CUTOUT NDT INSPECTION.

X-RAY external inspection of doubler sandwiched between fuselage skin and inner skin doubler. Skin lap areas. Frame, sill outer chord intersections. Fuselage skin beneath external steel stap. Skin and skin doubler around edge of door corners. Refer. DOC D6-48023 PART 2, 53-10-07 FIG 15.



sabena B707	Module: UPPR FUS /RADOME	A/C Reg :	Check :	 11F4000500 Page 4 of 4
	Oper. : RT-MP LC	Issuer : A43710	Cert.St.: 24828	
	Type : NDT INSP	Release Date: 10.10.2001		
Spec. : NDT INSP				

AFT ENTRY DOOR CUTOUT NDT INSP

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
3.	28914 CYC	E3	INS	AD 85-12-01 R1 rev 5439 MMS-328 530170 02002 rev 23/04/01 SSID 53-A40-06/IC rev N		
Check:						
Zones: 226						
Access: 1172 L						

AFT ENTRY DOOR CUTOUT NDT INSPECTION.

X-RAY external inspection of doubler sandwiched between fuselage skin and inner skin doubler. Skin lap areas. Frame, sill outer chord intersections. Fuselage skin beneath external steel stap. Skin and skin doubler around edge of door corners. Refer. DOC D6-48023 PART 2, 53-10-07 FIG 15.

