



sabena [®] B707	Module: HOR STAB + FL CT	A/C Reg :	Check :	 61F4000508
	Oper. : RT-MP LC			
	Type : NDT INSP	Issuer : A59513	Cert.St.: 50516	Page 1 of 2
Spec. : NDT INSP	Release Date: 03.05.2011			

HOR STAB CENTER SEC HINGE HOUS & DIAG BRACES NDT INSP

Execution / Start Date:	
End Date:	

MAINT	RII/INSP

sabena B707	Module: HOR STAB + FL CT	A/C Reg :	Check :	 61F4000508 Page 2 of 2
	Oper. : RT-MP LC			
	Type : NDT INSP	Issuer : A59513	Cert.St.: 50516	
	Spec. : NDT INSP	Release Date: 03.05.2011		

HOR STAB CENTER SEC HINGE HOUS & DIAG BRACES NDT INSP

					MAINT	RII/INSP	
Nr.	Hardtime	Task	Spec.	Related Documents			
1.		E4	NDT	AD 85-12-01 R1 rev 5439 MMS-328 533570 04000 rev 30/10/08 SB A3516 rev 0 SSID 55-A40-2/B rev N			
Check: C							
Zones: 137							
Access: 1185 L, 1187							
NRC YES <input type="radio"/> NO <input type="radio"/>		IF YES, NUMBER(S):					

HORIZONTAL STABILIZER CENTER SECTION HINGE HOUSING & DIAGONAL BRACES NDT INSPECTION.

Close visual HIGH FREQUENCY EDDY CURRENT internal inspection of all accessible areas of the hinge housing & diagonal braces for cracks. Particular attention should be given to hinge housing lower arm lugs, lower diagonal brace lugs & aft end of hinge housing from the lugs for the diagonal braces to the hinge bearing lug/cover plate.
Refer DOC D6-48023 part 6, 55-10-07, fig 5.

