



sabena B707	Module: ENGINE 2	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : SERVICING	Issuer : A43710	Cert.St.: 24828	O1H1000506
Spec. : MECHANIC	Release Date: 17.10.2001		Page 1 of 2	

ENG #2 FUEL D/I FILTER INSP

Execution / Start Date:	
End Date:	

MAINT **RII/INSP**

Pos	Mat. Type	P/N	IDN	Description	Qty	Unit
1	CONSUM	387622	120280	FILTER	1.00	EA
1	CONSUM	MS 9021-011	865732	O-RING	1.00	EA
1	CONSUM	MS 9021-021	865756	O-RING	1.00	EA
1	CONSUM	MS 9021-260	865745	O-RING	1.00	EA

sabena B707	Module: ENGINE 2	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : SERVICING	Issuer : A43710	Cert.St.: 24828	O1H1000506
	Spec. : MECHANIC	Release Date: 17.10.2001		Page 2 of 2

ENG #2 FUEL D/I FILTER INSP

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		E3 S	MEC	MMS-328 731001 A0102 rev 15/05/01		
Check: C						
Zones: 452						
Access:						

ENGINE #2 FUEL DE-ICING FILTER INSPECTION.

1. Remove fuel de-icing filter.
2. Inspect fuel de-icing filter. Replace if required.
3. Install fuel de-icing filter.
4. Check for leaks