



<b>sabena</b> <sup>®</sup> <b>B707</b>	Module: ENGINE 3	A/C Reg :	Check :	 <b>P1E0000500</b>
	Oper. : RT-MP LC			
	Type : * ZONAL INSP*	Issuer : A43710	Cert.St.: 24828	<b>Page 1 of 2</b>
Spec. : MECH. INSP	Release Date: 15.10.2001			

**ENG #3 FWD REV SYST INSP**

Execution / Start Date:	
End Date:	

MAINT	RII/INSP

<b>sabena</b> <b>B707</b>	Module: ENGINE 3	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : * ZONAL INSP*	Issuer : A43710	Cert.St.: 24828	<b>P1E0000500</b>
	Spec. : MECH. INSP	Release Date: 15.10.2001		<b>Page 2 of 2</b>

**ENG #3 FWD REV SYST INSP**

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		E3	INS	MMS-328 783002 A0103 rev 15/05/01		
<b>Check: C</b>						
<b>Zones: 453</b>						
<b>Access:</b>						
<p><b><u>ENGINE #3 FWD THRUST REVERSER SYSTEM INSPECTION.</u></b></p> <p>Close visual inspection of the forward thrust reverser consist mainly of the following: Check the cowl ring assembly for missing or loose rivets, skin cracks and freedom of travel, checking door linkage for freedom of travel, actuators for damaged piston rods and fan exhaust diaphragm upper turning vane for cracks.</p>						