



<b>sabena</b> <sup>®</sup> <b>B707</b>	Module: ENGINE 4	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : MEC-INSP	Issuer : A43710	Cert.St.: 24828	<b>Q1F2000514</b>
Spec. : MECH. INSP	Release Date: 16.10.2001		<b>Page 1 of 2</b>	

**ENG #4 NOSE COWL INSP**

Execution / Start Date:	
End Date:	

MAINT	RII/INSP

<b>sabena</b> <b>B707</b>	Module: ENGINE 4	A/C Reg :	Check :	
	Oper. : RT-MP LC	Issuer : A43710	Cert.St.: 24828	
	Type : MEC-INSP	Release Date: 16.10.2001	<b>Page 2 of 2</b>	
Spec. : MECH. INSP				

**ENG #4 NOSE COWL INSP**

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		E3	INS	MMS-328 541430 01000 rev 15/05/01 SAB 54-203 rev .		
Check: C						
Zones: 454						
Access:						
<p><b><u>CONDITION: NOSE COWL REMOVED.</u></b></p> <p><b><u>ENG. #4 NOSE COWL REMOVED.</u></b></p> <p>Detailed visual inspection for loose / missing fasteners. With cowl removed from power plant roll/ shake it on a soft surface (rubber, carpet, ...) to detect possible loose parts trapped in the cowl interior. Remove any loose parts.</p>						