



sabena [®] B707	Module: PYLON 3	A/C Reg :	Check :	
	Oper. : RT-MP LC			
	Type : NDT INSP	Issuer : A59513	Cert.St.: 46928	U1F4000501
	Spec. : NDT INSP	Release Date: 24.11.2005		Page 1 of 2

AD 85-12-01 rev . ENG #3 OVERWING SUP FIT CLEV LUG INSP

		MAINT	RII/INSP
Execution / Start Date:			
End Date:			

AD 85-12-01 rev . ENG #3 OVERWING SUP FIT CLEV LUG INSP

sabena B707	Module: PYLON 3	A/C Reg :	Check :	 U1F400501 Page 2 of 2
	Oper. : RT-MP LC	Issuer : A59513	Cert.St.: 46928	
	Type : NDT INSP	Release Date: 24.11.2005		
	Spec. : NDT INSP			

AD 85-12-01 rev . **ENG #3 OVERWING SUP FIT CLEV LUG INSP**

					MAINT	RII/INSP
Nr.	Hardtime	Task	Spec.	Related Documents		
1.		E4	NDT	AD 85-12-01 R1 rev 5439 MMS-328 544380 07000 rev 15.07.05 SB 57-3173 rev . SSID 57-A45-19 rev N.		
Check: C						
Zones: 457						
Access:						
NRC YES <input type="radio"/> NO <input type="radio"/>		IF YES, NUMBER(S):				

CONDITION: FAIRINGS REMOVED.

ENGINE #3 OVERWING SUPPORT FITTING CLEVIS LUGS INSPECTION.

Ultrasonic internal inspection of the overwing support fitting clevis lugs for cracks (DOC D6-48023 part 4, 54-40-07 fig 2).

